


Name of the equipment	Combined Temp Altitude & Humidity Test Chamber Make SERVATHIN, WEISS TECHNIK
Purpose/Use	Used for conducting Temp, Altitude & Humidity Test
Photograph	
Key specification	-70 to + 180 degree C 15% to 95% RH over 20 deg C to 85 deg C Alt climb rate 2000ft/min average from atmosphere to 10 m bar
Representative output, if possible	Graph of cyclic wave