


<b>Name of the equipment</b>	<b>Hot Cold Humidity Camber Make WEISS Model No WKL100/40</b>
<b>Purpose/Use</b>	<b>Used for Conducting Thermal Cycling &amp; Humidity test</b>
<b>Photograph</b>	
<b>Key specification</b>	<b>Temp range -40 to +150 degree centigrade Humidity range 10 % to 98 % RH</b>
<b>Representative output, if possible</b>	<b>Graph of Cyclic wave</b>