


Name of the Equipment / Facility	TEMPERATURE CHAMBERS
Purpose of Use	To perform High temperature testing, low temperature testing, temperature cycling and damped heat cycle tests
Photograph	
Key Specifications	<p>Temperature Range : -70 to +180⁰ C</p> <p>Humidity Range : 10 to 95% RH</p> <p>Max. Dimensions : 2m x 2m x 9m</p> <p>Max. Payload : 2000kg</p> <p>Cooling / Heating : 1 to 20 deg C/min</p> <p>Additional features: Environmental stress screening and Mould growth</p>